







Roofing - Current Issues

- Current Flat Installed originally 56 years ago
- Roof surface is at least 30 years old
- Water is penetrating into Building in several Places
- Roof Survey has determined roof as "Beyond Serviceable Life"
- Core samples show failure in a number of places
- Does not Conform to Current Building Regulations
- Glazing on roof is subject to imminent failure






Overview


STAT GADDESDE





Project reference: B171840/1 Project name: Great Gaddesden C of E VA School

BAUDER










Roof "A" over Entrance








Roof B with Rooflights over toilets







Roof B – Standing & Penetrating water & "Dormer" Window





Roof B- Glazed roof over Reading Area










Roof C - Yr ¾ Rooflight



Proposed Works

- Roof A
 - Roof Decking & Surface replaced with similar at slight gradient
 - Window overlooking Churchyard to be reduced in size grey window frame
- Roof B
 - Roof Surface to be replaced with similar matching gradient from Courtyard
 - 2 x roof lights replaced with low profile domed rooflights
 - 1970's Dormer window removed roofline and wall re-instated to original.
 - Sloped Glazed area removed (infill with new roof surface and replacement (grey powder-coat) roof lantern.
 - Glazed side screen (to Courtyard) replaced with matching Grey Powdercoated glazed screed.
- Roof C
 - Roof surface replaced with centre ridge pitch with shallow gradient
 - 1 x roof light replaced with low profile domed rooflight

View From West



Current




View From South



Current



View From East



Current



View From North



Current



Disused Dormer Window



Current

